

OUT 63015

1

25X1 S E C R E T 020940Z CITE [REDACTED] 1672

2. ORIGINAL NEGATIVE:

B. 9R SIDE: EDGE STATIC IS APPARENT ON BOTH INBOARD AND OUTBOARD EDGES OF THE FILM THROUGHOUT THE MISSION. PLUS DENSITY OVALS GENERALLY ASSOCIATED WITH ROLLER CHATTER ARE PRESENT ON BOTH EDGES THROUGHOUT. EMULSION LIFTS ARE PRESENT ON FRAMES 308 AND 309. ONE HEAT SPLICE OCCURRED IN THE FORMAT OF FRAME 670.

D. BOTH SIDES: EDGE STATIC AND ROLLER CHATTER ARE PRESENT THROUGHOUT THE MISSION. THE LAST TITLED FRAME IS 1352. MODE 5 OF CAMAERA OPERATION WAS UTILIZED THROUGHOUT. CYCLE RATE IS 4.5 SECONDS AND OVERLAP BETWEEN VERTICAL FRAMES IS APPROXIMATELY 60 PERCENT.

C. CLOUDS OBSCURE APPROXIMATELY 35 PERCENT OF THE MISSION.

蘇

NNNN

SECRET

DISTRIBUTION		
Cy. No.	Office	Action
5		
3,4,5	IND IAD	

GROUP 1
Excluded from automatic
downgrading and
declassification

1

Approved For Release 2006/01/31 : CIA-RDP78B03817A000100140027-0